

## Crimp nipples

### Crimp nipples

For quick screw. Zinc-plated steel. Type 01	For quick screw. Stainless steel. Type 02	Plug. Zinc-plated steel. Type 03 & 04	Plug. Brass. Type 03	Plug. Zinc-plated steel. Type 03 & 04	Swivel $\varnothing$ 10 mm. Stainless steel. Type 03 & 04	Swivel $\varnothing$ 11 mm. Stainless steel. Type 03 & 04	Swivel $\varnothing$ 11 mm. Zinc-plated steel. Type 03 & 04
<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN	<b>R+M Nr.</b> $\varnothing$ DN
100 001 942 6	040 001 942 6	316 95 6	316 951 6 6	316 951 8 6	316 93 6	316 94 6	316 961 8
100 001 940 8	040 001 940 8	316 98 8				316 96 8	
100 001 944 10	040 001 944 10					316 961 0 10	
	040 001 945 12						

## Crimp nipples

### Crimp nipples

### Seal kits crimp nipples

### Seal kit ST-44

	1/4" F. Stainless steel						
<b>R+M Nr.</b> $\varnothing$ DN		<b>R+M Nr.</b> $\varnothing$ VPE	<b>R+M Nr.</b> $\varnothing$ VPE	<b>R+M Nr.</b> $\varnothing$ TYP	<b>R+M Nr.</b> $\varnothing$ TYP	<b>R+M Nr.</b>	<b>R+M Nr.</b>
314 79 6		790 10 1	790 20 1	790 55 10 mm	790 58 10 mm	791 032 4	568 001 1
314 89 8		790 100 100	790 201 00 100	790 57 11 mm	790 59 11 mm		
314 99 10							

## Quick screws

### Quick screw for crimp nipples

- » M22 F.
- » Stainless steel.
- » Max. 500 bar

<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$
319 209 16.4	319 219 16.4	319 269 16.4	319 259 16.4	040 000 824 16.4		

### Quick screw for crimp nipples

- » Brass.
- » Max. 400 bar

<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$
319 20 16.4	319 21 16.4	319 26 16.4	319 25 16.4	010 000 721 16.4		

  

<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$	<b>R+M Nr.</b> $\varnothing$
319 231 17.3	319 201 17.3	200 042 154 16.4	319 10 16.4	319 80 16.4