

## Quick screw couplings

## Quick screw couplings with long centric nipple



M22 F : F.  
Max. 400 bar / 150 °C



M22 M : M. Long.  
Max. 400 bar / 150 °C

⊙
1/4"
3/8"

<b>R+M Nr.</b>	<b>i</b>
561 31	36 mm

<b>R+M Nr.</b>	<b>i</b>
565 311	40 mm
565 511	40 mm



M22 M : F. Long.  
Max. 400 bar / 150 °C



M22 M : 1/4" M. Long.  
Max. 400 bar / 150 °C

⊙
1/4"
3/8"

<b>R+M Nr.</b>	<b>i</b>
565 251	40 mm
565 401	40 mm

<b>R+M Nr.</b>	<b>i</b>
565 311 9	40 mm

## QSC with hexagon centric nipple



M22 F : F.  
Max. 400 bar / 150 °C



M22 F : F. With hexagon.  
Max. 400 bar / 150 °C

⊙
1/4"

<b>R+M Nr.</b>	<b>i</b>
560 50	41 mm

<b>R+M Nr.</b>	<b>i</b>
565 80	38 mm

Symbols **i** height **⊙** thread