

Quick screw couplings

Quick screw couplings with long centric nipple



M22 F : F.
Max. 400 bar / 150 °C



M22 M : M. Long.
Max. 400 bar / 150 °C

⊙
1/4"
3/8"

R+M Nr.	i
561 31	40 mm

R+M Nr.	i
565 311	40 mm
565 511	40 mm



M22 M : F. Long.
Max. 400 bar / 150 °C



M22 M : 1/4" M. Long.
Max. 400 bar / 150 °C

⊙
1/4"
3/8"

R+M Nr.	i
565 251	40 mm
565 401	40 mm

R+M Nr.	i
565 311 9	40 mm

QSC with hexagon centric nipple



M22 F : F.
Max. 400 bar / 150 °C



M22 F : F. With hexagon.
Max. 400 bar / 150 °C

⊙
1/4"

R+M Nr.	i
560 50	41 mm

R+M Nr.	i
565 80	38 mm

Symbols **i** height **⊙** thread