

Hose adaptor



M22 F : M22 M. K 2000. Brass.
Max. 400 bar

R+M Nr.	
565 66	



Plug 10 mm : M22 M.
Max. 250 bar

R+M Nr.	
559 910 2	



Plug coupling 10 mm : 3/8" M.
Max. 400 bar

R+M Nr.	
559 910 1	



Plug coupling 11 mm.
Max. 400 bar

R+M Nr.	⊙
559 911 12	1/2" M
559 911 38	3/8" M
559 911 22	M22 M
559 911 23	M22 F



Copper washer. K 2000

R+M Nr.	⊙
781 519 1	18.8 mm



O-ring

R+M Nr.	⊙
790 55	10 mm
790 57	11 mm



Back ring

R+M Nr.	⊙
790 58	10 mm
790 59	11 mm



M22 F : M22 M. Stainless steel.
Max. 400 bar / 150 °C

R+M Nr.	⊙
568 19	M22



Plug 11 mm : M22 M.
Max. 400 bar

R+M Nr.	⊙
316 961 1	190 mm



Plug 11 mm : M22 M.
Max. 400 bar

R+M Nr.	⊙
316 961 2	145 mm
316 961 3	150 mm



M27 M : M. Brass *.
Max. 400 bar

R+M Nr.	⊙
318 271 8	M18
318 272 1	M21



M24 M : 3/8" F. Brass *.
Max. 400 bar

R+M Nr.	
318 24	



Plug 10 mm : M22 M.
Max. 210 bar

R+M Nr.	⊙
316 951 0	190 mm



M22 M : plug. Brass.
Max. 250 bar / 100 °C

R+M Nr.	⊙
559 908 221	104 mm



M24 M : M. Brass *.
Max. 400 bar

R+M Nr.	⊙
318 241 8	M18
318 242 1	M21



O-ring

R+M Nr.	⊙
903 598 00	M27



O-ring

R+M Nr.	⊙
791 42	M24



M27 M : 3/8" F. Brass *.
Max. 400 bar

R+M Nr.	
318 27	

* not to be used with patented WAP / Venturi inserts