

Vacuum motors



1 stage. 230 V / 50 Hz.
Without cable, (Cable type 1 optional)

R+M Nr.	TYP	W	I	TI	∅
262 120 703	063700003	1200	136	46	143
262 120 701	064200001	1200	131	45	127



1 stage. 230 V / 50 Hz. Cable enclosed.
With thermo switch

R+M Nr.	TYP	W	I	TI	∅
262 080 101	203-19	800	110	30	110



1 stage. 230 V / 50 Hz.
Without cable, (Cable type 1 optional)

R+M Nr.	TYP	W	I	TI	∅
262 100 001	063200074	1050	122	45	132



1 stage. 230 V / 50 Hz.
Without cable, (Cable type 1 optional)

R+M Nr.	TYP	W	I	TI	∅
262 120 801	063200085	1200	128	51	132

Further vacuum motors are available on request.

Carbon brushes



R+M Nr.	suitable for R+M Nr.
262 000 102	262 080 102
262 000 102	262 100 102
262 000 102	262 100 003
262 000 102	262 120 102
262 000 102	262 120 202
262 000 102	262 120 302
262 000 202	262 140 102
262 000 202	262 120 702
262 000 302	262 045 001
262 000 402	262 100 202
262 000 402	262 120 602

R+M Nr.	suitable for R+M Nr.
262 000 502	262 100 001
262 000 101	262 110 002
262 120 1	262 101
262 120 1	262 120
262 120 3	262 120 902

Vacuum motor cable



Cable lug 6.3 : cable lug 4.8.
Cable 500 mm.
Cable type 1

R+M Nr.
262 000 001



Fork 3.5 : open.
Cable 300 mm.
Cable type 2

R+M Nr.
262 000 002



Wire end ferrule 2.8 : open.
Cable 300 mm.
Cable type 3

R+M Nr.
262 000 003

Seal



Rubber ring. For sealing and heightening the motor

R+M Nr.	∅	I
267 158 0	144 mm	20 mm

Motor cover



Cover for vacuum motors: 262 101, 262 120, 262 120 402, 262 120 502, 262 120 104

R+M Nr.
262 000 600

Symbols I height ∅ diameter TYP type