

Pompes haute-pression, Annovi Reverberi

Pompe HP série 132



P	←	U	KW	TYP
140	11	1.450	3,0	XT11.14N

R+M Nr.
170 701 4

Kits de réparation

01



Kit clapets
6 pièces

R+M Nr.
170 186 4

02



Kit haute-pression
pour 3 pistons

R+M Nr.
170 424 79

03



Kit joints d'huile
(6 pièces)

R+M Nr.	pièces
170 278 6	

04



Kit pistons céramique
pour 3 pistons

R+M Nr.	KØ	I
170 262 9	18	30

Pompe HP série 178



P	←	U	KW	TYP
150	15	1.450	4,0	XM15.15N

R+M Nr.
170 790 6

Kits de réparation

01



Kit clapets
6 pièces

R+M Nr.
170 186 4

02



Kit haute-pression
pour 3 pistons

R+M Nr.
170 274 7

03



Kit joints d'huile
(6 pièces)

R+M Nr.
170 187 2

04



Kit pistons céramique
pour 3 pistons

R+M Nr.	KØ	I
170 274 6	18	35

Pompes HP série 194



P	←	U	KW	TYP
200	26	1.450	9,2	XW26.20N
150	30	1.450	7,5	XW30.15N
200	30	1.450	10,0	XW30.20N
250	30	1.450	14,0	XW30.25N
150	42	1.450	11,8	XWL42.15N

R+M Nr.
170 200 59
170 201 79
170 200 60
170 211 37
170 210 60

Kits de réparation

01



Kit clapets
6 pièces

R+M Nr.
170 278 0
170 278 0
170 278 0
170 278 0
170 278 0
170 278 0

02



Kit haute-pression
pour 3 pistons

R+M Nr.
170 278 2
170 278 3
170 278 3
170 278 3
170 278 3
170 427 08

03



Kit joints d'huile
(7 pièces)

R+M Nr.
170 287 3
170 287 3
170 287 3
170 287 3
170 287 3
170 287 3

04



Kit pistons céramique
pour 3 pistons

R+M Nr.	KØ	I
170 265 0	20	45
170 189 1	22	45
170 189 1	22	45
170 189 1	22	45
170 189 1	22	45
170 184 9	28	45

Pompes HP série 228, type "RK"



P	←	U	KW	TYP
200	15	1.450	5,5	RK15.20HN
275	15	1.450	8,2	RK15.28HN
200	18	1.450	7,5	RK18.20HN
150	21	1.450	5,5	RK21.15HN

R+M Nr.
170 206 38
170 206 40
170 206 43
170 206 45

Kits de réparation

01



Kit clapets
6 pièces

R+M Nr.
170 286 4
170 286 4
170 286 4
170 286 4

02



Kit haute-pression
pour 3 pistons

R+M Nr.
170 185 7
170 185 7
170 188 7
170 188 8

03



Kit joints d'huile
(7 pièces)

R+M Nr.
170 185 5
170 185 5
170 185 5
170 185 5

04



Kit pistons céramique
pour 3 pistons

R+M Nr.	KØ	I
170 275 7	18	40
170 275 7	18	40
170 275 8	20	40
170 275 9	22	40

Les photos des pompes ou des kits de réparation ne sont pas contractuelles.
Leur aspect et leur composition peuvent varier selon les références d'articles.